

WELCH INDUSTRIES -- 24V Auxiliary Cabinet Wiring Diagram

Note: Motors run on direct 24Volts for High Speed, and run in Series (12Volts) for Low Speed.

